	Ty pe	Hits	Search Text	DBs	Time Stamp	Com ments	Error Defini tion	Error s
1	BR S	8	("4493975" "46599 07" "5547393" "559 0475" "D414364" " 6061923" "0036995 " "6189229" "20020 043003").PN.	USPAT; EPO; JPO	2004/09 /09 14:39			0
2	BR S	1	re36995.pn.	USPAT; EPO; JPO	2004/09 /09			0
3	BR S	8	("3964708" "4493975" "4659907" "4683369" "4802287" "4835879" "4868998" "4910385").PN.	USPAT	2004/09 /09 15:03			0
4	BR S	3	(34/96,97.ccls. 132/271.ccls.) and (support with cord)	USPAT; EPO; JPO	2004/09 /09 16:07			0
5	BR S	5	(34/96,97.ccls. 132/271.ccls.) and (hook with cord)	USPAT; EPO; JPO	2004/09 /09 16:06			0
6	BR S	7	(34/96,97.ccls. 132/27\$.ccls.) and (hook with cord)	USPAT; EPO; JPO	2004/09 /09 16:06			0
7	BR S	2		USPAT; EPO; JPO	2004/09 /09 16:06			0
8	BR S	6	(34/96,97.ccls. 132/27\$.ccls.) and (support with cord)	USPAT; EPO; JPO	2004/09 /09 16:08			0

	Ty pe	Hits	Search Text	DBs	Time Stamp	Com ments	Error Defini tion	Error s
9	BR S	3	((34/96,97.ccls. 132/27\$.ccls.) and (support with cord)) not ((34/96,97.ccls. 132/271.ccls.) and (support with cord))		2004/09 /09 16:07			0
10	BR S	204	(34/96,97.ccls. 132/27\$.ccls.) and (cord)	USPAT; EPO; JPO	2004/09 /09 16:08			0
11	BR S	1	(34/96,97.ccls. 132/27\$.ccls.) and (cord with hang)	USPAT; EPO; JPO	2004/09 /09 16:08			0
12	BR S	2	(34/96,97.ccls. 132/27\$.ccls.) and (cord with hang\$3)	USPAT; EPO; JPO	2004/09 /09 16:08			0
13	BR S	1	((34/96,97.ccls. 132/27\$.ccls.) and (cord with hang\$3)) not ((34/96,97.ccls. 132/27\$.ccls.) and (cord with hang))		2004/09 /09 16:12			0
14	BR S	31	(electric\$3 with cord) and (cord with hang\$3 with housing)	USPAT; EPO; JPO	2004/09 /09 16:16			0
15	BR S	574	(electric\$3 with cord) and (cord with hook)	USPAT; EPO; JPO	2004/09 /09 16:23			0
16	BR S	47	(electric\$3 with cord) and (cord with hook with hang\$3)	USPAT; EPO; JPO	2004/09 /10 13:31			0
17	BR S	3	("4673148" "5026016" "D343024").PN.	USPAT	2004/09 /09 16:38			0

	Ty pe	Hits	Search Text	DBs	Time Stamp	Com ments	Error Defini tion	Error s
18	BR S	32	("4193209" "38648 47" "5280679" "425 5871" "2734282" "2 184858" "2262274" "3287824" "535141 7" "2389822" "0647 485" "5873467" "D 451247" "D456951" "5084984" "D3027 44" "D299559" "47 54769" "D292625" "D286211" "D2869 26" "D453858" "44 64906").PN. ("5568691" "55156 21" "5249367" "513 0551" "5459944" "6 405387").PN.	USPAT; EPO; JPO	2004/09 /10 13:55			0

.

	Document ID	Issue Date	LITTE	Current OR	Current XRef	Inventor
1			Portable device for curing gel nail preparations	250/504 R	250/455.1 1; 250/492.1	Strait, Gloria
2	US 6490832 B1	2002 1210	Sliding door system	52/207	49/360	Fischbach, Stefan et al.
3	US 6408924 B1	2002 0625	Control system for a vertical vane covering for architectural openings	160/168. 1V	160/173V ; 160/177V	Anderson, Richard N. et al.
4	US 6325132 B1	2001 1204	Pantograph and control system for a vertical vane covering for architectural openings	160/173 V	160/178.1 V	Anderson, Richard N. et al.
5			Mounting system for coverings for architectural openings	160/178. 1V	160/902	Anderson, Richard N. et al.
6	US 6135188 A	2000 1024	Tassel for control system for a vertical vane covering for architectural openings	160/178. 1V	160/900	Anderson, Richard N. et al.
7		2000 0926	Fluorescent angle light	362/260	362/220; 362/285; 362/287; 362/427	Meltzer, Edward
8	US 6116322 A	2000 0912	Control system for a vertical vane covering for architectural openings	1/1		Anderson, Richard N. et al.
9	US 6098326 A	2000 0808	Locator sign	40/575	40/564	Campbell, III, Warren A.
10	US 5641223 A	1997 0624	Horticulture lamp	362/122	362/407; 362/410; 362/805	Rustebakke, Susan K.
11	US 5617087 A	1 :	Parking aid for parking vehicles in a covered garage	340/932. 2	116/29; 200/61.41 ;	Scott, Thomas J.
12			Stain detector apparatus and method	356/238. 3	250/485.1	Blackman, Stephen E. et al.
13	US 5519782 A	1996 0521	Headphone	381/370	381/385	Shinohara, Ikuo et al.
14	US 5480315 A		Rigidly securable water resistive electrical connector	:ZI 3 G/ / / I	439/278; 439/587	Martinelli, Leonard A.

	Document ID	Issue Date	Title	Current OR	Current XRef	Inventor
15	US 5454056 A	1 1	Luminous pull-cord for electrical switch operation	385/16	362/556; 385/147; 385/25; 385/88; 385/901; 385/92	Brothers, Harlan J.
16	US 5413161 A	1995 0509	Solar powered window shade	160/7	160/168.1 P; 160/168.1 R; 160/178.1 R	Corazzini, Warren
17	US 5344333 A		Locking apparatus for electrical plug connector assemblies	439/320	439/106; 439/312	Haag, Philip E.
18	US 5327592 A	1994 0712	Stationary nations lift	5/81.1R	254/362; 5/89.1	Stump, Floyd V.
19	US 5186653 A	1993 0216	Smoke alarm remote disconnect	439/500	340/628; 439/507; 439/638	Robert, Normand A.
20	US 5142508 A	1992 0825	Aquatic transducer system	367/141	310/337; 340/566; 367/136; 367/93	Mitchell, Thomas R. et al.
21	US 5012457 A	1991 0430	Aquatic transducer system	367/175	340/566; 367/182; 381/165; 381/334	Mitchell, Thomas R. et al.
22	US 4888639 A	1	Endoscope apparatus having integrated disconnectable light transmitting and image signal transmitting cord	348/69	600/109; 600/132	Yabe, Hisao et al.
23	US 4825047 A	111477	Temperature-responsive controller for waterbed mattress heaters	219/496	219/217; 219/419; 219/509; 236/57; 337/322; 5/422	Miles, Floyd D.
24	US 4551577 A	1985 1105	Retractable power center	174/57	174/48; 439/131	Byrne, Norman R.